Weldsale Platens

Stands and Tooling

Cross-Ribbed Underside and extra thick skirts add strength for **heavy duty work.**

Counter-Sunk Holes in corners for solid bolt down to stands. Entire top surface is usable.

Cast-In Sockets on the bottom of every square hole for fast, positive grip of bolt heads so tooling can be mounted quickly by one man.

Built Tough for Long Life

Platens bolt together easily into large work areas. Slotted holes have **raised bosses** to prevent sides from cracking.

A complete line of tooling and sturdy steel stands are available from stock.

STOCK SIZES: 2½'x5' 4'x4' 5'x5' 5'x6' 5'x8'

Flame-Cutting Table

An Inexpensive Alternative to Building Your Own

Use with flame cutting machines or hand cutting.

Standard and custom sizes available. Standard sizes are 4'x4' and 4'x6'.

Modular Design: Tables bolt together easily for longer or wider cutting area.

Every table is shipped with a set of Flame-Clear Pyramids.

Flame-Clear Pyramids

Add Economy to Flame Cutting

- **Reduce downtime** by protecting your flame-cutting table.
- You can use them **with oxy-fuel and plasma** cutting systems.
- Pyramids are **easy to re-position** and make heavy plates easier to move.
- Available from stock in a **variety of sizes.**

Call today for full information and free brochure.

WELDSALE

Weldsale Company

2151 Dreer Street; Philadelphia, PA 19125

Telephone: (215) 739-7474

Telex: 90-2006 JACO-PHA

—Division J. A. Cunningham Equipment., Inc.—

Circle **68** on Reader Service Card

Index to 1984 articles

By issue . . .

JANUARY

WFBG—1 1984 Welding and Fabricating Buyers Guide
152 Index to 1983 Articles

FEBRUARY

33 M & R Welding to the Rescue
39 Tulsa Office Tower Preserves a Landmark
43 Farasey Steel—Small Shop; Big Capacity
48 AWTAC Builds a Bridge from Lab to Shop Floor
53 Welded Beams—More Strength per Pound
62 Changes Come to ASME Section IX

MARCH

65 Putting a Head on a Nuclear Reactor
70 High-tech Ductware for Silicon Valley
73 Electrodes and Fixtures—Important RW Elements
77 Wear Testing of Hardsurfacing Alloys
83 How to Avoid Cold Laps in Short-Circuit GMAW
89 Welded Components Trim Big Fuel Bills
93 Know Your Welding NDT—Visual Inspection
100 W.E. Data Sheet No. 509—VT Checklist

APRIL

49 Automation Speeds Bending and Cutting
54 New Fabricating Machines Help Beat Competition
62 Plate Fabricators Take the Initiative
68 Good-looking Bridge for the Windy City
73 What We Have Learned About Fatigue of Welds
77 Spot Welding Setups Need Care, Accuracy
79 W.E. Data Sheet No. 510—Spot Welding Schedules

MAY

R-10 Guide to Robots and Robotic Systems
R-18 What Do Robots Need in Welding Equipment?
R-26 Tubesheet Overlays Perfect Every Time
R-32 Good News for Users of Resistance Welding
R-37 Army Personnel Carriers Refitted by Robots Repairs
R-43 Robots Pull Their Weight in Trailer Hitch Welding
83 GMA Welding Wins in HSLA Fabrication
87 W.E. Data Sheet No. 511—FCAW Schedules

JUNE

41 Here Comes the Big Inch
49 Should Fabricators Use Statistics for Process Control?
55 GTA Robot Welds Nuclear Fuel Elements

Weldsale Platens

Stands and Tooling

Cross-Ribbed Underside and extra thick skirts add strength for **heavy duty work.**

Counter-Sunk Holes in corners for solid bolt down to stands. Entire top surface is usable.

Cast-In Sockets on the bottom of every square hole for fast, positive grip of bolt heads so tooling can be mounted quickly by one man.

Built Tough for Long Life

Platens bolt together easily into large work areas. Slotted holes have **raised bosses** to prevent sides from cracking.

A complete line of tooling and sturdy steel stands are available from stock.

STOCK SIZES: 2½'x5' 4'x4' 5'x5' 5'x6' 5'x8'

Flame-Cutting Table

An Inexpensive Alternative to Building Your Own

Use with flame cutting machines or hand cutting.

Standard and custom sizes available. Standard sizes are 4'x4' and 4'x6'.

Modular Design: Tables bolt together easily for longer or wider cutting area.

Every table is shipped with a set of Flame-Clear Pyramids.

Flame-Clear Pyramids

Add Economy to Flame Cutting

- **Reduce downtime** by protecting your flame-cutting table.
- You can use them **with oxy-fuel and plasma** cutting systems.
- Pyramids are **easy to re-position** and make heavy plates easier to move.
- Available from stock in a **variety of sizes.**

Call today for full information and free brochure.

WELDSALE

Weldsale Company

2151 Dreer Street; Philadelphia, PA 19125

Telephone: (215) 739-7474

Telex: 90-2006 JACO-PHA

—Division J. A. Cunningham Equipment., Inc.—

Circle **68** on Reader Service Card

Index to 1984 articles

By issue . . .

JANUARY

WFBG—1 1984 Welding and Fabricating Buyers Guide
152 Index to 1983 Articles

FEBRUARY

33 M & R Welding to the Rescue
39 Tulsa Office Tower Preserves a Landmark
43 Farasey Steel—Small Shop; Big Capacity
48 AWTAC Builds a Bridge from Lab to Shop Floor
53 Welded Beams—More Strength per Pound
62 Changes Come to ASME Section IX

MARCH

65 Putting a Head on a Nuclear Reactor
70 High-tech Ductware for Silicon Valley
73 Electrodes and Fixtures—Important RW Elements
77 Wear Testing of Hardsurfacing Alloys
83 How to Avoid Cold Laps in Short-Circuit GMAW
89 Welded Components Trim Big Fuel Bills
93 Know Your Welding NDT—Visual Inspection
100 W.E. Data Sheet No. 509—VT Checklist

APRIL

49 Automation Speeds Bending and Cutting
54 New Fabricating Machines Help Beat Competition
62 Plate Fabricators Take the Initiative
68 Good-looking Bridge for the Windy City
73 What We Have Learned About Fatigue of Welds
77 Spot Welding Setups Need Care, Accuracy
79 W.E. Data Sheet No. 510—Spot Welding Schedules

MAY

R-10 Guide to Robots and Robotic Systems
R-18 What Do Robots Need in Welding Equipment?
R-26 Tubesheet Overlays Perfect Every Time
R-32 Good News for Users of Resistance Welding
R-37 Army Personnel Carriers Refitted by Robots Repairs
R-43 Robots Pull Their Weight in Trailer Hitch Welding
83 GMA Welding Wins in HSLA Fabrication
87 W.E. Data Sheet No. 511—FCAW Schedules

JUNE

41 Here Comes the Big Inch
49 Should Fabricators Use Statistics for Process Control?
55 GTA Robot Welds Nuclear Fuel Elements

59 Know Your Welding NDT—Leak Testing
63 W.E. Data Sheet No. 512—Leakage Rate Conversion
67 Cable-stayed Bridge Crosses the Mississippi

JULY
33 How to Choose Brazing Filler Metals
40 W.E. Data Sheet No. 513—AWS Brazing Alloys
43 Brazing Makes Light Frames for Jet Aircraft Engines
55 Pipeline Gives Miners a Breath of Fresh Air
59 Welding Sales Bottom Out in 1983

AUGUST
33 Worker Safety Makes Big Strides
38 Broad-based Program Protects Employees
45 Rob..ts 8 Reviewed—A No-nonsense Show
51 Welding Nickel Alloys? Use Two Electrode Types
55 Box Girder Design Keeps Traffic Moving
59 Programmed Controls Speed Furnace Welding
63 Keep Plant Computers Up and Humming

SEPTEMBER
35 QC Assures Reliability in Heavy Equipment
53 Know Your Welding NDT—Special Test Methods
57 W.E. Data Sheet No. 514—Hardness-Strength Conversion
63 Welding Sets Course for Shipbuilding Gains

OCTOBER
41 Automakers Move to Robots and Automatic Operations
50 A High-rise Soars in Downtown Cleveland
57 Welding Better with Pulsed Power
72 Welding an Aluminum Duct for a Fighter Plane

NOVEMBER
45 Laser Vision Robot Guides Welding Arc
49 Arc Welding Robot Cures Production Blahs
52 Hints for Success in Robotic Arc Welding
53 Pump Impellers Made Automatically
56 Automating Errors Out of Ship Propeller Refit
58 Automatic GMAW Joins Mining Bit Mountings
61 Know Your Welding NDT: Penetrant Testing
70 W.E. Data Sheet No. 515 — Penetrant Testing

DECEMBER
31 Computer-controlled Cutting: The Savings Multiply
37 Tough Nickel Alloys Yield to Plasma Cutting
41 Stressed-steel Skin Stiffens High Rise
44 Gas Metal Arc Welding Takes Care of HS Steels
48 Know Your Welding NDT — Selecting the Right Method
53 W.E. Data Sheet No. 516 — NDT Tests for Welds

continued on page 58

Circle 69 on Reader Service Card

NEW . . . from Weld-Aid Products

REVOLUTIONARY SOLID METAL "Cutting Tip Repair Tool" INCREASES TIP LIFE 700%

Re-Seat/Re-Face© is in reality two miracle tools in one! With the Re-Seat end you take all nicks and scratches off the gas seats. This eliminates leakage in the torch. Then with Re-Face you completely reface the cutting end by removing slag and other foreign matter for a better cut.

With Re-Seat/Re-Face© you'll get a minimum 7 times longer life out of every cutting tip. Your cutting tip costs can be lowered by 700% and more. Get Re-Seat/Re-Face© now!

Your dealer can supply, or contact . . .

WELD-AID PRODUCTS

14650 Dequindre • Detroit, MI 48212 • (313) 883-6977

Prevent Spatter Build-up!

Aerosol
- Silicone
- Non-Silicone

Gel
- Non-Silicone

Please Send Card for Brochure

WELD-AID PRODUCTS

14650 Dequindre
Detroit, MI 48212 • (313) 883-6977

"Engineered Welding Efficiency"

Circle 70 on Reader Service Card

Circle 71 on Reader Service Card

Step up to DC with a Lincoln AC/DC Arc Welder.

Big brother to the Lincoln AC-225-S. It's the ideal welding tool for do-it-yourself fabricating, maintenance, farm repair and construction, piping, and hardsurfacing.

And, it's great where DC works best: where high quality is required, for all-position welding, and sheet metal welding where a smooth arc is essential. Plus, it's ideal with stainless, low-hydrogen, non-ferrous, and many other electrodes.

The Lincoln AC/DC gives you a choice of DC or AC and runs on single phase 230-volt power. Standard features include input plug and receptacle, electrode holder, work clamp, and cables.

LINCOLN ELECTRIC
The power in welding since 1895.

Ask for a FREE Weldor's Guide complete with illustrated instructions and tips for better AC/DC welding. For your copy, write: The Lincoln Electric Company, Cleveland, Ohio 44117.

SIMULTANEOUSLY BEVEL, FACE AND COUNTERBORE PIPE TO 24" WITH...

THE TOUGH GUYS OF PIPE PREP TOOLS!



Tri Tool's 700 series pipe bevelers are rugged, go-anywhere lathes that take on the meanest end-prep jobs — from 2.5" I.D. to 24" O.D. heavy-wall pipe, depending on the model used. These precision bevelers never need pipe restraint, and they produce machine-finished weld preps that cut NDT reject rates dramatically.

Now with remote control! Models 710, 716, and 724 feature a remote control option that allows precise power and feed control from sites over 200 ft. from the working area.

TRI TOOL INC.

3806 Security Park Dr. / Rancho Cordova, CA 95670 / 916/351-0144
Toll free: 800/345-5015 (except CA, HI, AK). Telex 377-364

Circle 72 on Reader Service Card

1984 articles by subject

MONTH: Page number

ASME Code, revisions **2**: 63-65
ASTM specifications for HSLA steels **5**:85-88
Abrasive cutoff **12**:39
Accidents **8**:36-38
Acoustic emission testing **9**:54-56
Acoustic leak detection **6**:62
Air-carbon arc gouging **9**:66
Aircraft **10**:72-73
brazing **7**:43-45
engines **9**:22
Aluminum resistance welding (D.S.) **4**:78
Aluminum welding **5**:R-37—R-39 **10**:65, 72-73
American Welding Technology Application Center (AWTAC) **2**:48-50
Army personnel carriers **5**:R-37—R-39
Automated GMAW **3**:65-69 **8**:59-60
Automated welding, pipelines **6**:42-43
Automation **11**:53-59
Automobiles, HSLA in **5**:83-85
Automotive welding **10**:30, 41-48

Base metals identification **2**:34
Battery manufacture **3**:54-56
Bending **4**:49-60
Box girders **8**:55-57
Brazing
filler metals **7**:33-41
jet engine frames **7**:43-45
Brazing alloys, compositions and process temperatures (D.S.) **7**:40-41
Bridges **4**:68-71 **6**:67-70 **8**:55-57
Bubble leak testing **6**:62
Buildings **2**:39-41 **10**:51-54 **12**:41-43

Cans, fuel rod **6**:55-57
Cast iron, repair **2**:35-38
Cladding **5**:R-26—R-28
Clamps **3**:46
Cleaning of metals **8**:26-28
Cold laps **3**:83-87
Computers, care of **8**:63-64
Concrete mixers **12**:31-35
Controls for thermal cutting **3**:70-71 **10**:34 **12**:31-34
Convention, AWS **2**:57-61
Copper alloys, brazing fillers **7**:38
Cutting **4**:49-60

Defects **12**:48-50, 53
Diesel engines, quality control of **9**:36-38
Dissimilar metal joints **8**:51-52

continued on page 60

Circle 74 on Reader Service Card

ARCSTART

Flowmeter

INEXPENSIVE MULTI-GAS FLOW MEASUREMENT FOR GAS SHIELDED ARC WELDING AND OTHER INDUSTRIAL APPLICATIONS

- Easy to Read Hood and Flowtube made of High Strength Lexan® instead of Glass
- Four Color Coded Scales for multi-gas use: 0-200 CFH Helium, 0-70 CFH Argon, 0-60 CFH CO_2, 0-80 mm reference scale, (scales for other gases available upon request)
- Replaceable Precision Valve Assembly for Accurate Flow Metering and Process Control
- OEM and Wholesaler inquiries are invited

ARCSTART, INC.

P.O. Box 293, Feasterville, PA 19047
Phone (215) 322-5750

From the leaders in brazing technology.... invaluable data on 'HOW TO

REDUCE COSTS

of your

Metal Joining Assembly

This brazing and soldering data folder on metal joining brings you up to date with the latest materials, methods and equipment for reducing the total cost of your assembly.

Contains information on:

- Metal joint design
- Alloy selection guide
- Advantages of preforms
- Proper fixture design
- Semi-automated systems
- Feasibility studies

Yours for the asking— call toll free

800-558-3856 in WI (414) 769-6000

Lucas-Milhaupt, Inc.
A Handy & Harman Company

5656 S. Pennsylvania Avenue • Cudahy, WI 53110 • Telex 26789

See Our Catalog in THOMCAT

#MJ1184

Circle 75 on Reader Service Card

1984 articles by subject

continued from page 58

Duct fabrication **3**:70-71
Dye penetrants **6**:64
inspection **11**:61-71

Eddy current testing **9**:56-58
Electrical equipment **11**:40
Electrodes, resistance welding **3**:73-77
Electron beam welding **11**:40
Electroslag welding **2**:40
Energy conservation **6**:32
Equipment and accessories, buyers guide **1**:BG1-54

Fatigue **4**:73-75
Filler metals, brazing **7**:33-41
Fixturing, resistance welding **3**:73-77
Flux cored arc welding **2**:41 **3**:54-56 **10**:32 **11**:58-59
schedules for carbon, low-alloy steels (D.S.) **5**:87
Foundry welding **3**:50-52
Fracture mechanics **4**:74
Fume removal **8**:28
Fumes **8**:35-37
ventilation **8**:38-43

Gages **3**:98-99
Gas metal arc welding **5**:83-88 **6**:42-47 **10**:57-65 **12**: 44-46
by robot **5**:R-18—R-23 **10**: 44-46
of furnace chambers **8**:59-60
Gas tungsten arc welding **3**:89-92 **10**:65-68
robotic **6**:55-57
Grinding **4**:74-75
Guns for robotic arc welding **5**:R-20—R-21

HSLA steels, ASTM specifications for **5**:85-88
HSLA steels, GMAW of **5**:83-88
Halogen leak detection **6**:64
Hardness testing **9**:58-59
conversion chart (D.S.) **9**:57
Hardsurfacing **2**:33 **3**:79-81
Heat barriers **3**:54
Heat exchangers **3**:89-92
quality control of **9**:38-40
Heat treating **8**:26
Helium mass spectrometry **6**:64
High-strength steels **12**:44-46
Hydrogen in steel **12**:45
Hydrostatic testing **6**:47, 62

Jet engines, brazing frames of **7**:43-45
Job shop fabrication **2**:43-45

Laser beam cutting and welding **8**:45-46

continued on page 62

Severe Service Gloves & Mittens... HEAT'S UP?

PICK THE WINNER!

With the Elliott name on your side, you'll be ahead of the pack everytime the heat is up. If hot material handling, severe radiant heat, flux core or heavy mig welding are part of your job, our rugged gloves and mittens keep you on track.

The variety of heat-resistant materials and glove styles available from Elliott help you beat the hottest jobs. Our chrome tanned leathers and man-made fibers are lined for long wearing comfort and maximum protection.

Over long and short, you get a winning performance from Elliott. Our track record is protection.

ELLIOTT QUALITY PROTECTION



CRA-2

No. CRA-2 — Thermal cowhide leather is double chrome tanned for superior heat resistance and durability. Thermal glass heat lining. Additional flame-retardant fleece lining for comfort. Clute pattern, straight thumb with strap. 4" leather bell cuff.

No. HM-1 — Man-made aramid fabric contains **no asbestos**. Aluminized inner liner reflects heat. Wool fleece comfort liner. Lock stitched with Kevlar® thread. Straight thumb jumbo mitten is reversible. Replaceable slip-on shell available.

A2000

No. A2000 — Replaceable aluminized pad reflects heat and rays, protects fully lined side split cowhide glove. Gunn pattern, wing thumb glove has one piece back of aluminized PFR rayon. Complete inseam construction lock stitched with Kevlar®. Welting in all vulnerable seams. In pairs or singly.

HM-1

No. A2001 — Mixed pair combines protection where most needed with dexterity. One No. A2000 glove with snap-on pad (see above). Other mated all leather glove has one piece back with full semi-sock fire-resistant thermal lining. Kevlar® sewn, lock stitched, welting in all vulnerable seams. Right or left hand combinations.

A2001

WRITE FOR LITERATURE

Place Your Hand and Trust in An Elliott Glove

ELLIOTT
GLOVE COMPANY, INC.
504 Pecor Street • Oconto, Wisconsin 54153
Toll-Free Phone: 1-800/558-8194
WI, AK, HI Phone: 414/834-5622

Circle 77 on Reader Service Card

1984 articles by subject

continued from page 60

Leak testing **6**:59-65
Liquid penetrant inspection **11**:61-71

Maintenance and repair welding **2**:33-38 **9**:24
Mechanized welding **3**:50
Medical equipment **11**:49-51
Metal transfer **10**:57-59
Military vehicles **11**:45-48 12:44-46
Mining equipment **11**:58-59
Multiple operator power **11**:30

Nickel alloys **8**:51-52 **12**:37-39
Nondestructive evaluation **3**:84-87
Nondestructive testing **9**:53-59 **11**:61-71 **12**:48-54
  leaks **6**:59-65
  visual **3**:44
  visual inspection **3**:93-101
Nondestructive tests (D.S.) 12:53
Nuclear fuel rods **6**:55-57

Nuclear plants, leak testing **6**:65
Nuclear power **3**:65-69

OSHA practices **8**:33-36

Peel test **2**:55
Pipe ventilation shaft 7:55-57
Pipelines
  HSLA **5**:88
  leak testing **6**:64-65
  welding **6**:41-47
  nickel alloys **12**:37-39
Plasma arc cutting **3**:89-92
  steel sheet **3**:70-71
  nickel alloys **12**:37-39
Plasma arc welding **3**:56 **9**:22,24
Plate bending **3**:46-48
Power supplies **10**:57-68
Press brakes **4**:49-60
Pressure/vacuum decay leak testing **6**:62
Pressure vessels **3**:46
  overlays **5**:R-26—R-28
Programmable controllers **5**:R-39
Pulsed power **10**:57-68
Pulsed spray transfer GMAW **3**:65-69
Pumps **11**:53-55

Quality control **6**:49-53 **9**:35-42

Radiography **3**:85-87
Railroad repair **2**:37-38
Repair welding **2**:33-38 **6**:30-32
Research and development **2**:48-50
Residual stress **4**:73-75
Resistance welding **3**:73-77 **4**:77-80 **5**:R-32—R-33 **8**:45-46 **10**:41-48
  high-frequency **2**:53-55

continued on page 64

robotic RSW 10:41-48
Resistance welding guns for robots 5:R-32—R-33
Retorts 3:50
River Bend power station 3:65-69
Robotic welding 5:R-1—R-48 6:55-57 11:45-52
robotic RSW 10:41-48
robotic GMAW 10:44-46
Robots 5: R-1—R-48 8:45-48 11:56-57
Safety training 8:38-43
Sales of welding equipment 7:59-61
Seam tracking 11:45-48
Shears 4:49-60
Sheet metal fabrication 10:62,67
Shielded metal arc welding 3:89-92 6:42-47
Safety and health 8:33-43
Shielding gas 3:84-85
for robotic arc welding 5:R-20
Ship propellers 11:56-57
Shipbuilding 9:63-67 12:44-46
Short-circuit GMAW 3:83-87
Short-circuiting transfer, GMAW 10:58
Side-bend testing 3:85-87
Spray transfer, GMAW 10:58-59
Stainless-carbon steel welds 3:89-92
Stainless steel 3:54
braze fillers (table) 7:36
resistance welding (D.S.) 4:78
Statistical process control 6:49-53
Steel, resistance welding (D.S.) 4:78
Structural beam fabrication 2:53-55
Structural welding 2:39-41
Submerged arc welding 2:40 6:42-47
Surface defects in welds, types of 3:95-97
Surfacing 3:56,79-81 9:22,24
Synergic power supplies 10:60-61

Tanks 4:36,38
Testing, peel test 2:55
hydrostatic 6:47
Thermal cutting 2:43-45 10:34 12:31-35
Titanium 9:22
Tool repair 2:36-38
Trailer hitches 5: R-43—R-46
Transformer guns for RSW 10:46-47
Tube bending 3:52
Turbine-generators, quality control of 9:40-42
Tubing, inspection 3:44

Ultrasonic testing 3:85-87

Ventilation 3:48 8:28,35-37 9:27
Vision, robot 8:46 11:45-48
Visual examination, tools for 3:97-99
Visual inspection checklist (D.S.) 3:100

Water-jet cutting 8:45-46
Wear 3:79-81
Wear testing 3:79-81
Weldmetal remelting 4:74-75
Weld peening 4:74-75
Weld overlays by robot 5:R-26—R-28
Weld profiles 3:96
Welding costs 9:64-65
Welding machines 6:32
Welding schedules, FCAW of carbon, low-alloy steels (D.S.) 5:87
Welding sequence 3:69
Wire feeders for robotic arc welding 5:R-21
Wires for robotic welding 5:R-19—R-20
Workmanship standards, visual inspection 3:94

(D.S. = Data Sheet)

The duplicator that eliminates layout

THE HEVIPLATE DUPLICATOR
Fabricates Heavy Plate Parts Up To 1-1/8" Thick

W.A. Whitney's HEVIPLATE™ DUPLICATOR eliminates manual layout or handling between layout and punching. A typical base plate can be completely fabricated in less than 3 minutes. Subsequent parts can be duplicated in less than 1 minute each using the first part as the template. Inventory can be greatly reduced since little or no setup time is required.

Model 7130-A has 100 ton press capacity with a 30" x 60" positioning area (includes "X" and "Y" scale readouts and stylus for duplicating first parts). Punching rate is 10 or 12 holes per minute.

You also benefit from increased productivity, predictable quality, elimination of complicated procedures and reduced operator fatigue.

Write or call **W.A. WHITNEY CORP., 650 Race St., P.O. Box 958, Rockford, IL 61105-9990, Phone 815/964-6771.**



W.A.WHITNEY
AN ESTERLINE COMPANY
Productivity Through Innovation

Circle 79 on Reader Service Card